



2N[®] EasyRoute Fax over T.38 theory and troubleshooting





Discussed topics

- Theory
 - Analog fax, fax terminals V.21 – V.29, protocol T.30
 - Fax over IP, protokol T.38
 - SIP, SDP T38 handshake
 - UDPTL, T38
- EasyRoute Fax
 - Parameters analysis
 - Analytic tools
 - Troubleshooting



Theory, analog fax

T.4

Picture coding

Protocol T.30

Fax control protocol

Transmitting by HDLC frames

Training and transmission speed arrangement between terminals

HDLC

V.21

300bps
FSK

V.27ter

2400bps, 4800bps
DPSK

V.29


4800, 7200, 9600 bps
QAM

V.17

7200, 9600, 12200,
14400 bps
TCM




Theory, analog fax, T.30




Theory, T.30, frame structure


- T.30 properties
 - Half duplex
 - Frames are transmitted by HDLC protocol
 - Frames are always transferred by V.21 terminal



T0828600-97/d033

Figure 10/T.30








Fax over IP, protokol T.38


- T.38 purpose: transfer all fax phases (T.30, training and image data) va IP network
- Connection initiation via SIP or H323





T.38 packet

- T.38 structure
 - UDPTL – redundancy security mechanism
 - Primary packet
 - Secondary packet (doubling of -n last packets)
 - IFP – encapsulation of T.30 data



a) Layered model of IFP/UDPTL/UDP/IP packet




T.38 Transmission

- Normal SIP – VoIP call
- Phase A (CNG, CED) via RTP stream
- After CNG, CED tones SIP T.38 reinvite
- After successful T.38 reinvite (OK 200) RTP stream is finished transmission of T.38 is started



Figure 5-12 T.38 Fax Relay Switchover for SIP





Important T.38 terms

- **T38 Data Rate Management:**
Method of training frequency transmission
 - Transferred TCF : training frequency is sent as an image data also via IP network.
 - Local TCF: training is proceed on the gateways separately and only the indicator is transferred via IP network
- **T38 UDP EC:**
Error correction mechanizm of UDPTL protocol.
 - Correction by redundancy packets: the copy of previous packets is sent to the secondary IFP packet
 - FEC: Forward Error Correction. Function XOR is applied on the added packet



Important parameters of the EasyRoute T.38

- **TCF**
Handling of training signal. Almost always Transferred
- **Error Correction**
Error correction of UDPTL protocol. Almost always Redundancy
- **Reinvite tone**
For which tone EasyRoute should proceed T.38 reinvite (CNG, CED or DIS frame)
- **Reinvite direction**
Who should send T.38 reinvite. Caller or callee. According to the ITU T.38 it should be callee.
- **Always DIS reinvite**
No matter what was the previous determination flow EasyRoute will always try to send T.38 reinvite always after DIS frame
- **UDP Flood**



How to make T.38 working

- Set up default parameters
 - Set up call routing to VoIP (in default everything is to GSM)
 - Set up SIP account
 - Try SIP call in both directions. In case of problems try to disable Firewall
 - Try T.38 Fax in both directions
- common problem: we didn't get to the T.38 reinvite step. Try another reinvite direction or another reinvite tone.



Troubleshooting

- SIP
 - If SIP call was initiated properly?
 - Network quality evaluation
 - Ping response time
 - Quality of VoIP call (jitter buffer is fulfilled)
 - If phase A of RTP stream is finished (you can hear CNG, CED in the handset)?
 - If the both-sides RTP stream is seen in the Wireshark?
 - If the proper T.38 reinvoke was proceed?
 - Response OK 200
 - UDPTL protocol is agreed
 - Media parameters T38FaxRateManagement and T38FaxUdpEc are agreed for the same value



Troubleshooting

- T.38
 - Is T.38 stream seen on the same agreed UDP ports?
 - On which phase fax stopped working?
 - Didn't get DCS therefore it's sending DIS repeatedly
 - Didn't get the training confirmation (CFR, FTT) therefore it resends DCS and training sequence repeatedly
 - ...
- **Fax listening**: Incoming and outgoing frames could not be overlapped. That's the result of the bad synchronization.